

## SOLDERING RECOVER TRAY Type BR50



### Setting:

This set include :

- 1 Cabinet with welded hood (epoxy paint RAL 7031)
- 1 Titanium tank (capacity 50kgs) with external plated resistors
- 1 Stainless worktable 20/10
- \*4 ingot maker (for ingots of 4.5kgs)
- 1 Pack of tools (Ladle, scraper, skimer)

Option : **1 Hoover (run continuously when the tank is heating)**

\* Option ingot maker for ingot with hanging hole +90€HT (each ingot maker)

NOTA :The oxydes recovery must be delivered into the ingot maker for this purpose,  
it allows to produce ingots at the tank form (saving time for melting)